

School	Item	Item Description	Date	Result	Action
High School	#048	Girl's Locker Room Door 29 PE Office Sink	8/4/2021	Tested Above Threshold	Retest
	#050	Room 350 Sink	8/4/2021	Tested Below Threshold	Retest
	#094	Cafe-Kitchen Serving Line - Hand Sink	8/4/2021	Tested Above Threshold	Retest
	#FH003	Field House Inside Rear Hose BIB	8/4/2021	Tested Above Threshold	Sign Posted Not Potable Water
	#FH005	Field House Outside Bubbler	8/4/2021	Tested Above Threshold	Retest
	#FH006	Field House Westside of Track Water Supply	8/4/2021	Tested Above Threshold	Retest
Middle School	#2AMS	Boy's South Gym Hallway to Locker Room Bubbler	8/4/2021	Tested Above Threshold	Retest
	#5AMS	Girl's South Gym Hallway to Locker Room Bubbler	8/4/2021	Tested Above Threshold	Retest
	#19AMS	North Gym Girl's Locker Room Bubbler	8/4/2021	Tested Above Threshold	Retest
	#59AMS	Room 111 Right Sink	8/4/2021	Tested Above Threshold	Retest
	#61AMS	113 Hallway Bubbler	8/4/2021	Tested Above Threshold	Retest
	#63AMS	127 Hallway Bubbler	8/4/2021	Tested Above Threshold	Retest
	#98AMS	DO Men's Bathroom from Left B Sink	8/4/2021	Tested Above Threshold	Retest
	#117AMS	213 Hallway Bubbler	8/4/2021	Tested Above Threshold	Retest
	#121AMS	201 Hallway Bubbler	8/4/2021	Tested Above Threshold	Retest
	#135AMS	212 Hallway Bubbler	8/4/2021	Tested Above Threshold	Retest
	#145AMS	Kitchen by Salad Bar Are Ice Machine	8/4/2021	Tested Above Threshold	Retest
	#164AMS	Kitchen Hose Bib	8/4/2021	Tested Above Threshold	Sign Posted Not Potable Water
Smallwood	#SM17	Room 226 Sink	8/4/2021	Tested Above Threshold	Replace Outlet/Retest
	#SM81	Kitchen 3 Bay Sink Faucet Right Side	8/4/2021	Tested Above Threshold	Retest
	#SM89	Bubbler Across From Room 220	8/4/2021	Tested Above Threshold	Retest
	#SM99	Bubbler Room 149	8/4/2021	Tested Above Threshold	Retest
	#SM111	Hose Bib Inside Door 5	8/4/2021	Tested Above Threshold	Sign Posted Not Potable Water
	#SM112	Hose Bib Upper Garage	8/4/2021	Tested Above Threshold	Sign Posted Not Potable Water
Windermere	#WB16	Room 216 Sink	8/4/2021	Tested Above Threshold	Retest
	#WB18	Room 208 Sink	8/4/2021	Tested Above Threshold	Retest
	#WB23	Room 203 Sink B	8/4/2021	Tested Above Threshold	Retest
	#WB38	Room 256 Sink	8/4/2021	Tested Above Threshold	Retest
	#WB82	Room 110 Sink	8/4/2021	Tested Above Threshold	Retest
	#WB107	Kitchen - Pot Filler Over Stove	8/4/2021	Tested Above Threshold	Outlet to be Taken Out of Service
	#WB109	Room 230 Bubbler	8/4/2021	Tested Above Threshold	Outlet to be Taken Out of Service
	#WB110	Room 231 Bubbler	8/4/2021	Tested Above Threshold	Outlet to be Taken Out of Service
	#WB111	Room 226 Bubbler	8/4/2021	Tested Above Threshold	Outlet to be Taken Out of Service
	#WB112	Room 209 Bubbler	8/4/2021	Tested Above Threshold	Outlet to be Taken Out of Service
	#WB114	Room 144 Bubbler	8/4/2021	Tested Above Threshold	Outlet to be Taken Out of Service
#WB117	Room 100 Bubbler	8/4/2021	Tested Above Threshold	Outlet to be Taken Out of Service	